

**Inspection Report**







Report No.: XYS-130516  
 Supplier : XY-GLOBAL

Inspection Date: 15<sup>th</sup> Jun, 2013  
 Inspector: Leo

Inspection only for: PO . XYS-130516 Item No. XY11SL023	<b>Inspection Result:</b> PASS
------------------------------------------------------------	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11SL023	8000PCS	5% inspection	0pcs	No failure	8000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product	6. The test report



Safety is our serious job for our worker and engineer team

