

**Inspection Report**

**Report No.:** XYS-130831  
**Supplier :** XY-GLOBAL

**Inspection Date:** 11<sup>th</sup> Sep-, 2013  
**Inspector:** LEO

Inspection only for: PO . XYS-130831 Item No. Fishing gear wheel	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
Fishing gear wheel	<b>30PCS</b>	100% inspection	30pcs	No failure	30pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4. Product
	
5. Product :	6. Product:

	CNC  CNC  CNC  CNC  CNC  CNC
	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
	CNC
	gague
	+/- 0.01MM
	T / T 50  50  T / T
	CNC
	20-25  T / T 50
	1.Name: OEM
	2.Process:
	3.Material: AL6061 AL6065 AL6063 AL7075
	4.Surface  :
	5.Tolerance: 0.01 -/+  MM
	6  Quality: 100
	7.Specification: OEM
	8.  30-25 :
	9.  accessoried
	10.  AUSTRIAL
	11.  : ISO 9001
	1. 10
	2.
	3. kinds  sureface finishment  available
	4.
	5.
	6.
	7.
	CNC  :
	CNC  :
	CNC  : ISO9001
	: