

□□□□□□□□□□□□□□□□

### Inspection Report

**Report No.:** XYS-130719  
**Supplier :** XY-GLOBAL

**Inspection Date:** 15<sup>th</sup> Aug, 2013  
**Inspector:** Leo

Inspection only for: PO . XYS-130711 Item No.XY-9921300	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-9921300	<b>500PCS</b>	5% inspection	0pcs	No failure	500pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

品名	ADC12A380 OEM
品番	ADC12A380
規格	
仕様	
材質	
公差	+/-0.01
公差	T / T 50
公差	
公差	
公差	20-25 T / T 50
公差	
1.Name	
2.Process	
	ADC12A380
4.	
5.Tolerance	±0.01
6.	100
7.Specification	serice
8.	25-30
9.	accessoried
10.	Austrial
11&NBSP;	ISO 9001
1	10 ISO
2	
3	kindls available
4	
5	
6	
7	
	ISO9001
	OEM