

□□□□□□□□□□□□□□3□

**Inspection Report**







**Report No.:** XYS-130514  
**Supplier :** XY-GLOBAL

**Inspection Date:** 20<sup>th</sup> Jun, 2013  
**Inspector:** Leo

Inspection only for: PO . XYS-130514 Item No.XY-130074	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-130074	<b>10PCS</b>	10% inspection	0pcs	No failure	10pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

