

Inspection Report







Report No.: XYSK-140505
 Supplier : XY-GLOBAL

Inspection Date: 3th Jun, 2014
 Inspector: Leo

Inspection only for: PO . XYSK-140505 Item No. XY11WD010	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11WD010	5000PCS	1% inspection	0pcs	No failure	5000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Dimensions report

Company Name	Company Name OEM Product Name
Material	ADC12 A380
Surface	Surface Finish
Quantity	Quantity
Process	CNC Process
Tolerance	+/- 0.01MM
Quality	Quality 100
Specification	Specification OEM
Lead Time	Lead Time 30-25
Accessories	Accessories
ISO	ISO 9001
Company	Company
1. Name	1. Name
2. Process	2. Process
3. Material	3. Material
4. Surface	4. Surface
5. Tolerance	5. Tolerance
6. Quality	6. Quality
7. Specification	7. Specification
8. Lead Time	8. Lead Time
9. Accessories	9. Accessories
10. ISO	10. ISO
11. Company	11. Company
1. 10	1. 10
2. 2	2. 2
3. kinds	3. kinds
4. Surface	4. Surface
5. 5	5. 5
6. 6	6. 6
7. 7	7. 7
8. 8	8. 8
9. 9	9. 9
10. 10	10. 10
11. 11	11. 11