

**Inspection Report**







Report No.: XYAN-150406  
 Supplier : XY-GLOBAL

Inspection Date: 5<sup>th</sup> May-, 2015  
 Inspector: LEO

Inspection only for: PO . XYAN-150406    Item No. XY21ZC074	<u>Inspection Result:</u> <b>PASS</b>
--	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC074	8000pcs	7% inspection	0pcs	No failure	8000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:





High qualified surface treatment can make your parts perfect !!!

