

Inspection Report

Report No.: XYLA-150413
 Supplier : XY-GLOBAL

Inspection Date: 18th May, 2015
 Inspector: Leo

| | |
|---|-----------------------------------|
| Inspection only for: PO . XYLA-150413 Item No. XY31PC023 | <u>Inspection Result:</u> PASS |
|---|-----------------------------------|

| Description | Finished Q'ty | Sample Size | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| XY31PC023 | 25000PCS | 1% inspection | 0pcs | No failure | 25000pcs |

| |
|--|
| Appearance Inspection : |
| No failure, |
| Dimension Inspection: |
| No failure , below measurement report for reference. |
| Assembly Test: |
| No failure |
| Inspection Summary |
| The inspection sample plan is 100% inspection. |

Digital photo records :

| | |
|---|---|
|  |  |
| 1. Packing | 2. Product |
|  |  |
| 3. Product | 4 Product |
|  |  |
| 5. Product: | 6. report |

| | |
|---|---|
| <p> 1. Name: " 2. Process: 3. Material: AL6065 AL6063 AL6061 AL7075 4. Surface: 5. Tolerance: 0.01-/+ 6. 7. Specification: OEM 8- 9- 10. 11- </p> | <p> 1. Name: " 2. Process: 3. Material: AL6065 AL6063 AL6061 AL7075 4. Surface: 5. Tolerance: 0.01-/+ 6. 7. Specification: OEM 8- 9- 10. 11- </p> |
| <p> 1-10 2- 3- 4- 5. 6- 7- </p> | <p> 1-10 2- 3- 4- 5. 6- 7- </p> |
| <p> ISO9001 </p> | <p> ISO9001 </p> |



High qualified surface treatment can make your parts perfect !!!

