

□□□□ □□□□ □□□□□□ □□□□□□□□ □□□□ □□□ □□□□□□□□□□

Inspection Report







Report No.: XYS-130523
Supplier : XY-GLOBAL

Inspection Date: 15th Jun, 2013
Inspector: Leo

Inspection only for: PO . XYS-130523 Item No.XY-1300015	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-1300015	500PCS	5% inspection	0pcs	No failure	500pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

