

□□□ □□□□□□ □□□□ □□□□ □□ □□□ □□□□□□□□□ □□□□□ □□□□

### Inspection Report

Report No.: XYS-130314  
 Supplier : XY-GLOBAL

Inspection Date: 14<sup>th</sup> Apr, 2013  
 Inspector: Leo

Inspection only for: PO . XYS-130314 Item No.XY-1315400	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-1315400	300PCS	10% inspection	0pcs	No failure	300pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

