

**Inspection Report**

Report No.: XYSL-140618  
 Supplier : XY-GLOBAL

Inspection Date: 25<sup>th</sup> Jul, 2014  
 Inspector: Leo

Inspection only for: PO . XYSL-140618 Item No. XY11WD041	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11WD041	10000PCS	5% inspection	0pcs	No failure	10000pcs







**Appearance Inspection :**  
 No failure,

**Dimension Inspection:**  
 No failure , below measurement report for reference.

**Assembly Test:**  
 No failure

**Inspection Summary**  
 The inspection sample plan is 100% inspection.

Digital photo records :

	
<p>1. Packing</p> 	<p>2. Product</p> 
<p>3. Product</p> 	<p>4 Product</p> 
<p>5. Product</p>	<p>6. The test report</p>

Company Name	Company Name OEM Product Name Product Description
Material	Material ADC12 A380
Quantity	Quantity
Product Description	Product Description
Process	CNC Process
Surface Treatment	Surface Treatment gague
Tolerance	Tolerance +/- 0.01MM
Lead Time	Lead Time T / T 50
Quality	Quality 100
Specification	Specification OEM
Accessories	Accessories
ISO 9001	ISO 9001
1. Name	1. Name OEM Product Name
2. Process	2. Process
3. Material	3. Material ADC12 A380
4. Surface	4. Surface gague
5. Tolerance	5. Tolerance 0.01 +/- 0.01MM
6. Quality	6. Quality 100
7. Specification	7. Specification OEM
8. Lead Time	8. Lead Time 30-25
9. Accessories	9. Accessories accessoried
10. AUSTRIAL	10. AUSTRIAL
11. ISO 9001	11. ISO 9001
1. 10	1. 10
2. 2	2. 2
3. kinds	3. kinds sureface finishment available
4. 4	4. 4
5. 5	5. 5
6. 6	6. 6
7. 7	7. 7
ISO 9001	ISO 9001
1. 1	1. 1
2. 2	2. 2
ISO 9001	ISO 9001
1. 1	1. 1
OEM	OEM