

**Inspection Report**






Report No.: XYDA-150319  
 Supplier : XY-GLOBAL

Inspection Date: 15<sup>th</sup> Apr, 2015  
 Inspector: Leo

Inspection only for: PO . XYDA-150319 Item No. XY31CY036	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY036	20000PCS	1% inspection	0pcs	No failure	20000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :										
										
1. Packing	2. Product									
										
3. Product	4 Product									
	<p><b>XY-GLOBAL</b> 深圳市真朴电子科技有限公司                  XY Electronics Technology Co.,Ltd</p> <table border="1"> <tr> <td>Client: XYDA-150319</td> <td>Product Name: XY31CY036</td> <td>Inspection Date: 2015.04.15</td> </tr> <tr> <td>Part: XY31CY036</td> <td>Lot: XY31CY036</td> <td>Inspector: Leo</td> </tr> <tr> <td>Quantity: 20000</td> <td>Material: Brass</td> <td>Customer: XY-GLOBAL</td> </tr> </table> <p>Inspection Item: XY31CY036</p> <p>Inspection Method: 100% inspection</p> <p>Inspection Result: PASS</p> <p>Inspection Summary: No failure</p> <p>Inspection Report: XYDA-150319-XY31CY036</p>	Client: XYDA-150319	Product Name: XY31CY036	Inspection Date: 2015.04.15	Part: XY31CY036	Lot: XY31CY036	Inspector: Leo	Quantity: 20000	Material: Brass	Customer: XY-GLOBAL
Client: XYDA-150319	Product Name: XY31CY036	Inspection Date: 2015.04.15								
Part: XY31CY036	Lot: XY31CY036	Inspector: Leo								
Quantity: 20000	Material: Brass	Customer: XY-GLOBAL								
5. Product:	6. report									

