



Inspection Report

Report No.: XYK-130829
 Supplier : XY-GLOBAL







Inspection Date: 29th Sep-, 2013
 Inspector: LEO

| | |
|--|-----------------------------------|
| Inspection only for: PO . XYK-130829 Item No.1330026 | Inspection Result: PASS |
|--|-----------------------------------|

| Description | Finished Q'ty | Sample Size | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|-----------------|--------------|---------------------|-----------------|
| 1330026 | 50PCS | 100% inspection | 0pcs | No failure | 50pcs |

| |
|--|
| Appearance Inspection : No failure, |
| Dimension Inspection: No failure , below measurement report for reference. |
| Assembly Test: No failure |
| Inspection Summary The inspection sample plan is 100% inspection. |

Digital photo records :

| | |
|---|--|
|  |  |
| 1. Packing | 2. Product: |
|  |  |
| 3. Product: | 4. Product: |
|  |  |
| 5. Product : | 6. Product: |

