

Inspection Report







Report No.: XYGA-150314
 Supplier : XY-GLOBAL

Inspection Date: 18th Apr., 2015
 Inspector: LEO

| | |
|--|-----------------------------------|
| Inspection only for: PO . XYGA-140314 Item No. XY21ZC054 | <u>Inspection Result:</u> PASS |
|--|-----------------------------------|

| Description | Finished Q'ty | Sample Size | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| XY21ZC054 | 8000pcs | 7% inspection | 0pcs | No failure | 8000pcs |

| |
|--|
| Appearance Inspection : No failure, |
| Dimension Inspection: No failure , below measurement report for reference. |
| Assembly Test: No failure |
| Inspection Summary The inspection sample plan is 100% inspection. |

| | |
|---|---|
| Digital photo records : | |
|  |  |
| 1. Packing | 2. Product: |
|  |  |
| 3. Product: | 4. Product: |
|  |  |
| 5. Product : | 6. Inspection report: |

