

Inspection Report

Report No.: XYN-130814  
 Supplier : XY-GLOBAL

Inspection Date:02<sup>th</sup>- Sep-, 2013  
 Inspector:LEO

Inspection only for: PO . XYN-130814    Item No.1400190	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1400190	5000PCS	1% inspection	0pcs	No failure	5000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

	CNC  CNC  CNC  CNC  CNC  CNC
	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
	CNC CNC
	gague
	+/- 0.01MM
	T / T 50 50 T / T
	T / T 50 25-20
1.Name:	OEM
2.Process:	
3.Material:	AL6061 AL6065 AL6063 AL7075
4.Surface	
5.Tolerance:	0.01 -/+ MM
6. Quality:	100
7.Specification:	OEM
8.	30-25
9.	accessoried
10.	AUSTRIAL
11.	ISO 9001
1.	10
2.	
3.	sureface finishment available
4.	
5.	
6.	
7.	
CNC	
CNC	
CNC	ISO9001
	CNC