

Inspection Report

Report No.: XYAD-140516
 Supplier : XY-GLOBAL

Inspection Date: 25th Jun, 2014
 Inspector: Leo

Inspection only for: PO . XYAD-140516 Item No.200-10-870	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
200-10-870	20000PCS	1% inspection	0pcs	No failure	20000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

Company Name	Company Name OEM [Link]
Material	ADC12 A380
Quantity	
Product Description	
Process	CNC
Material	ADC12 A380
Surface	gauge
Tolerance	+/- 0.01MM
Quality	100%
Specification	ISO 9001
Lead Time	20-25 days
Payment	T/T
Shipping	
1.Name:	OEM [Link]
2.Process:	CNC
3.Material:	ADC12 A380
4.Surface	gauge
5.Tolerance:	0.01 +/- 0.01MM
6. Quality:	100%
7.Specification:	OEM
8. Lead Time:	30-25 days
9. Payment:	T/T
10. Shipping:	AUSTRIAL
11. Certification:	ISO 9001
[Link]	
1. 10	
2.	
3. kinds surface finishment	available
4.	
5.	
6.	
7.	
[Link]	
[Link]	
[Link]	
ISO9001	
[Link]	
OEM	