

**Inspection Report**

**Report No.:** XYN-131117  
**Supplier :** XY-GLOBAL

**Inspection Date:**10<sup>th</sup> Dec-, 2013  
**Inspector:**KEN

Inspection only for: PO . XYN-131117 Item No.XY-MST-035	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-MST-035	35000PCS	1% inspection	0pcs	No failure	35000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

Material	Material: AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
Surface	Surface: gague
Tolerance	Tolerance: +/- 0.01MM
Quality	Quality: 100
Specification	Specification: OEM
Material	Material: AL6061 AL6065 AL6063 AL7075
Surface	Surface: gague
Tolerance	Tolerance: +/- 0.01MM
Quality	Quality: 100
Specification	Specification: OEM
Material	Material: AL6061 AL6065 AL6063 AL7075
Surface	Surface: gague
Tolerance	Tolerance: +/- 0.01MM
Quality	Quality: 100
Specification	Specification: OEM
Material	Material: AL6061 AL6065 AL6063 AL7075
Surface	Surface: gague
Tolerance	Tolerance: +/- 0.01MM
Quality	Quality: 100
Specification	Specification: OEM
Material	Material: AL6061 AL6065 AL6063 AL7075
Surface	Surface: gague
Tolerance	Tolerance: +/- 0.01MM
Quality	Quality: 100
Specification	Specification: OEM
Material	Material: AL6061 AL6065 AL6063 AL7075
Surface	Surface: gague
Tolerance	Tolerance: +/- 0.01MM
Quality	Quality: 100
Specification	Specification: OEM