

□□□□□□ □□□□□□□□ □□□□□ □□□□ ADC12 □□□□ □□□□□□□□□□

### Inspection Report

**Report No.:** XYS-130928  
**Supplier :** XY-GLOBAL






**Inspection Date:** 25<sup>th</sup> Oct, 2013  
**Inspector:** Leo

Inspection only for: PO . XYS-130920 Item No.3240100	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
3240100	3000PCS	5% inspection	0pcs	No failure	3000pcs

<b>Appearance Inspection :</b>
No failure.
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

