

□□□□ □□□□□□□□ □□

Inspection Report

Report No.: XYA-130814
 Supplier : XY-GLOBAL

Inspection Date: 15th Sep-, 2013
 Inspector: LEO

| | |
|---|-----------------------------------|
| Inspection only for: PO . XYA-130814 Item No.130353 | Inspection Result: PASS |
|---|-----------------------------------|

| Description | Finished Q'ty | Sample Size | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| 130353 | 1000PCS | 3% inspection | 0pcs | No failure | 1000pcs |

| |
|--|
| Appearance Inspection : No failure, |
| Dimension Inspection: No failure , below measurement report for reference. |
| Assembly Test: No failure |
| Inspection Summary The inspection sample plan is 100% inspection. |

Digital photo records :

| | |
|--------------|-------------|
| | |
| 1. Packing | 2. Product: |
| | |
| 3. Product: | 4. Product: |
| | |
| 5. Product : | 6. Product: |