

□□□□□□ □□□□□□ □□□□ □□□□□□□□□□ □□□□ □□□□ □□□□ □□□□□ □□□□□ □□□□□

### Inspection Report

**Report No.:** XYD-130703  
**Supplier :** XY-GLOBAL







**Inspection Date:** 10<sup>th</sup> Aug, 2013  
**Inspector:** Leo

Inspection only for: PO . XYS-130703 Item No.XY-956400	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-956400	<b>800PCS</b>	5% inspection	0pcs	No failure	800pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

