

Inspection Report







Report No.: XYSL-150607
 Supplier : XY-GLOBAL

Inspection Date: 10th July, 2015
 Inspector: Leo

Inspection only for: PO . XYSL-150607 Item No. XY31XL005	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31XL005	32000PCS	1% inspection	0pcs	No failure	32000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

工廠名稱: 廣東省 佛山市 順德區 均安鎮 均安工業區 均安鎮 均安工業區 均安鎮 均安工業區
 工廠地址: 廣東省 佛山市 順德區 均安鎮 均安工業區 均安鎮 均安工業區 均安鎮 均安工業區
 工廠電話: 0757-86288888
 工廠傳真: 0757-86288888
 工廠網址: http://www.9001.com.cn
 工廠代碼: 9001
 工廠認證: ISO9001
 工廠服務: OEM



Safety is our serious job for our worker and engineer team

