

Inspection Report

Report No.: XYD-130813
Supplier : XY-GLOBAL

Inspection Date:10th- Sep-, 2013
Inspector:LEO

Inspection only for: PO . XYD-130813 Item No.1400038	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1400038	20000PCS	1% inspection	0pcs	No failure	20000pcs

Appearance Inspection : No failure.
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

	CNC CNC CNC CNC
	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
	CNC
	gague
	+/- 0.01MM
	T / T 50 50 T / T
	T / T 50 25-20
1.Name:	OEM
2.Process:	
3.Material:	AL6061 AL6065 AL6063 AL7075
4.Surface	
5.Tolerance:	0.01 +/- MM
6. Quality:	100
7.Specification:	OEM
8.	30-25
9.	accessoried
10.	AUSTRIAL
11.	ISO 9001
1. 10	
2.	
3. kinds sureface finishment available	
4.	
5.	
6.	
7.	
CNC	
CNC	
CNC	ISO9001