

Inspection Report







Report No.: XYSL-150705
 Supplier : XY-GLOBAL

Inspection Date: 8th Aug, 2015
 Inspector: Leo

Inspection only for: PO . XYSL-150705 Item No. XY31XL025	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31XL025	8000PCS	1% inspection	0pcs	No failure	8000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

...	...
...	...
...	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
...	...
...	...
...	...
...	...
...	...
...	...
...	...
...	...
...	+/-0.01
...	T/T 50 ... 50 % T/T
...	...
...	...
...	...
...	...
...	20-25 50 ... % T/T
...	...
1.Name:	"..."
2.Process:	...
3.Material:	AL6065 AL6063 AL6061 AL7075
4.Surface:	...
5.Tolerance:	0.01-/+
6.	100 ...
7.Specification:	OEM
8-	30-25 ...
9-	...
10.	...
11-	ISO 9001
...	...
1-10	...
2-	...
3-	...
4-	...
5.	...
6-	...
7-	...
...	...
...	...
...	...
...	ISO9001
...	...
...	...

Safety is our serious job for our worker and engineer team

