

Inspection Report

Report No.: XYDA-140517
Supplier : XY-GLOBAL

Inspection Date: 10th Jun, 2014
Inspector: Leo

Inspection only for: PO . XYDA-140517 Item No.1464290	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1464290	6000PCS	1% inspection	0pcs	No failure	6000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

Company Name	Company Name OEM
Material	ADC12 A380
Surface	gauge
Process	CNC
Tolerance	+/- 0.01MM
Quality	100
Specification	OEM
Lead Time	30-25
Accessories	accessoried
Country of Origin	AUSTRIAL
Certification	ISO 9001
Payment Terms	T / T 50
Minimum Order	10
Lead Time	30-25
Surface Finish	sureface finishment
Material	ADC12 A380
Process	CNC
Tolerance	+/- 0.01MM
Quality	100
Specification	OEM
Lead Time	30-25
Accessories	accessoried
Country of Origin	AUSTRIAL
Certification	ISO 9001
Payment Terms	T / T 50
Minimum Order	10
Lead Time	30-25
Surface Finish	sureface finishment
Material	ADC12 A380
Process	CNC
Tolerance	+/- 0.01MM
Quality	100
Specification	OEM