

6061□□□□□□



Inspection Report

Report No.: XYK-130810
Supplier : XY-GLOBAL







Inspection Date:12th Sep-, 2013
Inspector:LEO

Inspection only for: PO . XYK-130810 Item No.1300420	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1300420	500PCS	3% inspection	0pcs	No failure	500pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

品名	铝合金 CNC 加工零件
材料	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
形状	见附图
数量	10000 件
公差	±0.01mm
表面处理	阳极氧化
检验标准	ISO 9001
交货期	10 天
付款方式	预付 30%
其他要求	无
1.Name	铝合金 CNC 加工零件
2.Process	CNC 加工
3.Material	AL6061 AL6065 AL6063 AL7075
4.Tolerance	±0.01mm
5.Quantity	10000 件
6.Specification	ISO 9001
7.Surface Treatment	阳极氧化
8.Delivery Time	10 天
9.Payment Terms	预付 30%
10.Other Requirements	无
11.ISO 9001	符合
品名	
1. 数量	10000 件
2. 公差	±0.01mm
3. 表面处理	阳极氧化
4. 检验标准	ISO 9001
5. 交货期	10 天
6. 付款方式	预付 30%
7. 其他要求	无
品名	
1. 数量	10000 件
2. 公差	±0.01mm
3. 表面处理	阳极氧化
4. 检验标准	ISO 9001
5. 交货期	10 天
6. 付款方式	预付 30%
7. 其他要求	无