

□□A380□□□□□□□□□□

Inspection Report







Report No.: XYS-130519
Supplier : XY-GLOBAL

Inspection Date: 09th Jun, 2013
Inspector: Leo

Inspection only for: PO . XYS-130519 Item No.XY-1303580	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-1303580	800PCS	5% inspection	0pcs	No failure	800pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

0000	0000 0000000000 0000000000 0000000000OEM0000000000 0000
00	0 ADC120A3800
00	0 000000
0000	0 000000000000000000000000 0000
00	0 0000000000
0000	00 000000000000000000 000000000000000000
0000	00 0000000000gague000000000000 000000000000000000000000 000000000000000000000000 0
000000	00
00/00	+/-0.0100
00	T / T 5000000000500T / T00000000
0000	00 000000000000000000000000 000000000000000000
00	000 00000000000000000000 000000000000000000
00	0000 00
00	20-25&NBSP;0 T / T 50000000
0000	00 000000
1.Name0 000000000000	
2.Process0000000000	
0000000000ADC120A3800	
4.0000000000000000000000 00000	
5.Tolerance0000±0.0100	
6.000000100000	
7.Specification000serice0000000000	
8000000025-3000000000	
90000000000000000000 00accessoried00000000	
10000000000000000000Austrial000000	
11&NBSP;000ISO 9001	
000000	
1001000000ISO00	
2000000000	
30000000000kindls0available	
40000000000000	
50000000	
60000000	
7000000000000000	
000000	
00000000&NBSP;0000000000 00	
0000000000000000	
0000000000000000ISO9001	
0000000000000000 00	
0000000000000000OEM0000	