

Inspection Report







Report No.: XYI-140324
 Supplier : XY-GLOBAL

Inspection Date: 19th Apr, 2014
 Inspector: Leo

Inspection only for: PO . XYI-140324 Item No.144031	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
144031	5000PCS	1% inspection	0pcs	No failure	5000pcs

Appearance Inspection :
No failure.
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

品名	加工機用部品OEM部品
品番	ADC12 A380
仕様	
材質	
加工	
公差	CNC加工
表面処理	gague
公差	
公差	+/-0.01
公差	T / T 50 T / T
公差	
公差	
公差	
公差	T / T 50 20-25 NBSP
公差	
1.Name	
2.Process	
	ADC12 A380
4.	
5.Tolerance	±0.01
6.	100
7.Specification	serice
8.	25-30
9.	accessoried
10.	Austrial
11&NBSP;	ISO 9001
1	10 ISO
2.	
3.	kindls available
4.	
5.	
6.	
7.	
	NBSP;
	ISO9001
	OEM