

Inspection Report

Report No.: XYSL-130507
 Supplier : XY-GLOBAL

Inspection Date: 8th Jun, 2013
 Inspector: Leo

Inspection only for: PO . XYSL-130507 Item No. XY11SL004	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11SL004	3000PCS	5% inspection	0pcs	No failure	3000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product	6. The test report

品名	XXXXXXXXXXXXX XXXXXXXXXXXXXXXXXXXXXXXXXXXX XXXXXXXXXXX OEMXXXXXXXXXX
品名	ADC12/A380
品名	XXXXXXXXXX
品名	XX
品名	XXXXXXXXXXXX
品名	XX XXXX
品名	XX XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
品名	XXXXXXXXXX
品名	+/-0.01%
品名	XXXXXXXX50XXXXXXXXXXXXXXXXXXXXXXXX50XXXX
品名	XX
品名	XX
品名	XXXX
品名	XXXXXXXX50XXXXXXXX25XXXX
品名	XXXXXXXXXXXXXXXXXXXX
1.品名	XXXXXXXXXXXX
2.品名	XXXXXXXXXXXXXXXXXXXXXXXXXXXX
3.品名	ADC12/A380
4.品名	XXXXXXXXXXXXXXXXXXXXXXXXXXXX XXXX
5.品名	±0.01%
6.品名	100XXXX
7.品名	XXXXXXXXXXXXXXXXXXXXXXXXXXXX
8.品名	25-30%
9.品名	XXXXXXXXXXXXXXXXXXXXXXXXXXXX XXXXXXXXXXXXXXXXXXXXXXX
10.品名	XXXXXXXXXXXXXXXXXXXXXXXXXXXX
11.品名	ISO 9001
品名	
1.10品名	ISOXXXX
2.品名	XXXXXXXXXXXXXXXXXXXX
3.品名	XXXXXXXXXXXXXXXXXXXX
4.品名	XXXXXXXXXXXX
5.品名	
6.品名	
7.品名	XXXXXXXXXXXX
品名	
品名	XXXXXXXXXXXXXXXXXXXX
品名	XXXXXXXXXXXX
品名	ISO9001
品名	XXXXXXXXXXXXXXXXXXXX
品名	OEMXXXXXXXXXXXX