

□□□□□□□□

**Inspection Report**

**Report No.:** XYS-130523  
**Supplier :** XY-GLOBAL







**Inspection Date:** 15<sup>th</sup> Jun, 2013  
**Inspector:** Leo

Inspection only for: PO . XYS-130523 Item No.XY-1300015	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-1300015	<b>500PCS</b>	5% inspection	0pcs	No failure	500pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

品名	ADC12 A380 OEM
品番	ADC12 A380
仕様	
数量	
単位	
材質	
公差	+/-0.01
表面処理	T / T 50
検査方法	
納入期	
備考	
1.Name	ADC12 A380
2.Process	
3.品番	ADC12 A380
4.公差	+/-0.01
5.Tolerance	+/-0.01
6.表面処理	T / T 50
7.Specification	
8.検査方法	
9.付属品	accessories
10.納入期	
11.&NBSP;ISO 9001	
備考	
1.品番	ISO
2.仕様	
3.種類	kindls available
4.数量	
5.単位	
6.材質	
7.公差	
備考	
品番	&NBSP;
仕様	
検査方法	ISO9001
納入期	
備考	OEM