

Inspection Report

Report No.: XYBA-140921
 Supplier : XY-GLOBAL

Inspection Date: 18th Oct, 2014
 Inspector: LEO

Inspection only for: PO . XYBA-140921 Item No. XY21ZC014	Inspection Result: PASS
--	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC014	1000PCS	7% inspection	0pcs	No failure	1000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

〇〇	〇〇〇〇〇〇CNC〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇CNC〇〇
〇〇	〇〇〇 AL6061 AL6065〇〇AL6063〇〇AL7075〇〇SUS304〇〇SUS303〇〇SUS316〇
〇〇	〇〇〇〇〇〇〇〇
〇〇〇〇	〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇
〇〇	〇〇〇〇〇〇〇〇〇
〇〇〇〇	〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇 〇〇〇〇
〇〇〇〇	〇〇〇
〇〇〇〇〇	〇〇〇〇〇〇〇
〇〇/〇〇	+/-0.01〇〇
〇〇〇〇	〇〇〇〇〇50〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇50〇〇〇〇〇〇〇
〇〇〇〇	〇〇〇
〇〇	〇〇
〇〇	〇〇〇〇〇
〇〇	〇〇〇〇〇〇50〇〇〇〇〇〇〇〇25〇〇〇〇〇
〇〇〇〇	〇〇〇〇〇〇〇
1.	〇〇〇〇〇〇〇〇〇〇〇〇CNC〇〇
2.	〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇
	〇〇〇〇〇〇〇AL6061 AL6065〇〇AL6063〇〇AL7075〇
4.	〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇 〇〇〇〇〇
5.	〇〇〇〇〇〇〇±0.01〇〇
6.	〇〇〇〇〇〇100〇〇〇〇〇
7.	〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇
8.	〇〇〇〇〇〇〇25-30〇〇
9.	〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇 〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇
10.	〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇
11.	〇〇〇〇〇〇〇〇〇〇〇ISO 9001
	〇〇〇〇〇
1.10.	〇〇〇〇〇〇〇〇〇〇ISO〇〇
2.	〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇
3.	〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇
4.	〇〇〇〇〇〇〇〇〇〇〇
5.	〇〇〇〇〇〇
6.	〇〇〇〇〇〇〇
7.	〇〇〇〇〇〇〇〇〇〇〇〇〇〇
	〇〇〇〇〇
	〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇
	〇〇〇〇〇〇〇〇〇〇〇〇〇
	〇〇〇〇〇〇〇〇〇〇〇ISO9001
	〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇〇
	〇〇〇OEM〇〇〇〇〇〇