

**Inspection Report**

Report No.: XYLA-150313  
 Supplier : XY-GLOBAL






Inspection Date: 18<sup>th</sup> Apr, 2015  
 Inspector: Leo

Inspection only for: PO . XYLA-150313 Item No. XY31PC009	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31PC009	25000PCS	1% inspection	0pcs	No failure	25000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

物料	数控加工CNC
材料	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
公差	±0.05
表面处理	阳极氧化
最小壁厚	0.8mm
最小孔径	0.5mm
最小孔距	0.5mm
最小槽宽	0.5mm
最小槽深	0.5mm
最小倒角	C0.5
最小圆角	R0.5
最小长度	50mm
最小直径	50mm
最小重量	50g
最小数量	25件
最小交期	3-5天
1. 数控加工CNC	
2. 阳极氧化	
材料 AL6061 AL6065 AL6063 AL7075	
4. 公差 ±0.05	
5. 公差 ±0.01	
6. 公差 100%	
7. 表面处理	
8. 壁厚 25-30%	
9. 最小壁厚 0.8mm	
10. 最小孔径 0.5mm	
11. 符合ISO 9001	
物料	
1.10 符合ISO	
2. 公差	
3. 公差	
4. 公差	
5. 公差	
6. 公差	
7. 公差	
物料	
符合ISO9001	
符合ISO9001	
符合OEM	

Safety is our serious job for our worker and engineer team

