

**Inspection Report**

Report No.: XYAN-150313  
 Supplier : XY-GLOBAL

Inspection Date: 16<sup>th</sup> Apr-, 2015  
 Inspector: LEO

Inspection only for: PO . XYBA-150313      Item No. XY21ZC100	<b>Inspection Result:</b> <b>PASS</b>
--	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC100	12000pcs	7% inspection	0pcs	No failure	12000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

項目	詳細内容
項目	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
項目	詳細内容
項目	詳細内容
項目	詳細内容
項目	詳細内容
項目	詳細内容
項目	詳細内容
項目	詳細内容
項目	±0.01
項目	50 50
項目	詳細内容
項目	詳細内容
項目	50 25
項目	詳細内容
1. CNC	
2. 詳細内容	
AL6061 AL6065 AL6063 AL7075	
4. 詳細内容	
5. ±0.01	
6. 100	
7. 詳細内容	
8. 25-30	
9. 詳細内容	
10. 詳細内容	
11. ISO 9001	
項目	
1.10 ISO	
2. 詳細内容	
3. 詳細内容	
4. 詳細内容	
5. 項目	
6. 項目	
7. 詳細内容	
項目	
詳細内容	
詳細内容	
ISO9001	
詳細内容	
OEM	

Safety is our serious job for our worker and engineer team

