

**Inspection Report**

Report No.: XYSL-150720  
 Supplier : XY-GLOBAL







Inspection Date: 25<sup>th</sup> Aug, 2015  
 Inspector: Leo

Inspection only for: PO . XYSL-150720 Item No. XY31XL040	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31XL040	13000PCS	1% inspection	0pcs	No failure	13000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

0000	0000000CNC00000000000000CNC00
00	000 AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
00	00000000
0000	00000000000000000000000000000000
00	0000000000
0000	00000000000000000000000000000000 0000
0000	0000000000000000000000 00
000000	00000000
00/00	+/-0.01
0000	0000500000000000000000005000000
0000	00
00	00
00	000000
00	00000050000000250000
0000	00000000
1.0000000000CNC00	
2.000000000000000000	
0000000AL6061 AL6065AL6063AL7075	
4.00000000000000000000 000000	
5.0000000±0.01	
6.0000001000000	
7.00000000000000000000000000000000	
8.00000025-3000	
9.0000000000000000000000 000	
10.000000000000000000000000	
11000000000ISO 9001	
000000	
1.10000000ISO00	
2.000000000000000000000000	
3.000000000000000000000000	
4.000000000000	
5.000000	
6.0000000	
7.0000000000000000	
000000	
00000000000000000000000000000000	
0000000000000000	
00000000000ISO9001	
000000000000000000000000	
00OEM00000000	

Safety is our serious job for our worker and engineer team

