

Inspection Report

Report No.: XYN-130814
Supplier : XY-GLOBAL

Inspection Date: 02th Sep, 2013
Inspector: LEO

Inspection only for: PO . XYN-130814 Item No.1400190	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1400190	5000PCS	1% inspection	0pcs	No failure	5000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

品名	品名 CNC加工品 CNC加工品
材質	AL6061 AL6065 AL6063 AL7075 &NBSP; SUS304 SUS303 SUS316
形状	
仕様	
加工	CNC加工品
加工	gague加工品
加工	
公差	+/-0.01
加工	T / T 50 T / T 50 T / T
加工	
加工	
加工	T / T 50 20-25 NBSP
加工	
1.Name CNC加工品	
2.Process	
AL6061 AL6065 AL6063 AL7075	
4.	
5.Tolerance ±0.01	
6.100	
7.Specification serice	
8.25-30	
9.accessoried	
10.Austrial	
11&NBSP; ISO 9001	
品名	
1.10 ISO	
2.	
3.kinds available	
4.	
5.	
6.	
7.	
品名	
&NBSP;	
ISO9001	