

Inspection Report







Report No.: XYSL-150616
 Supplier : XY-GLOBAL

Inspection Date: 20th July, 2015
 Inspector: Leo

Inspection only for: PO . XYSL-150616 Item No. XY31XL014	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31XL014	9000PCS	1% inspection	0pcs	No failure	9000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

品名	品名CNC加工品CNC加工品
品番	品番 AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
仕様	仕様
材料	材料
寸法	寸法
公差	公差
表面	表面
検査	検査
納期	納期
単位	単位
梱包	梱包
価格	価格
送料	送料
備考	備考
1. CNC加工	
2. 品名	
品名AL6061 AL6065 AL6063 AL7075	
4. 公差	
5. 公差 ±0.01	
6. 公差 100	
7. 公差	
8. 公差 25-30	
9. 公差	
10. 公差	
11. ISO 9001	
品名	
1.10. ISO	
2. 品名	
3. 品名	
4. 品名	
5. 品名	
6. 品名	
7. 品名	
品名	
品名	
品名	
品名ISO9001	
品名	
品名OEM	

Safety is our serious job for our worker and engineer team

