

Inspection Report

Report No.: XYAN-150419
 Supplier : XY-GLOBAL

Inspection Date: 22th May-, 2015
 Inspector: LEO

Inspection only for: PO . XYAN-150419 Item No. XY21ZC085	Inspection Result: PASS
--	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC085	12000pcs	7% inspection	0pcs	No failure	12000pcs

Appearance Inspection :
 No failure,

Dimension Inspection:
 No failure , below measurement report for reference.

Assembly Test:
 No failure

Inspection Summary
 The inspection sample plan is 100% inspection.

Digital photo records :

	
<p>1. Packing</p>	<p>2. Product:</p>
	
<p>3. Product:</p>	<p>4. Product:</p>
	
<p>5. Product :</p>	<p>6. Inspection report:</p>

品名	精密CNC加工品
材質	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
仕様	標準仕様
公差	標準公差
表面処理	標準表面処理
検査	標準検査
包装	標準包装
納期	標準納期
品質保証	品質保証
送料	標準送料
その他	
1.	精密CNC加工
2.	
	AL6061 AL6065 AL6063 AL7075
4.	
5.	± 0.01
6.	100
7.	
8.	25-30
9.	
10.	
11.	ISO 9001
1.10.	ISO
2.	
3.	
4.	
5.	
6.	
7.	
	ISO9001
	OEM



High qualified surface treatment can make your parts perfect !!!

