

□□□□□□□□



Inspection Report

Report No.: XYK-130819
 Supplier : XY-GLOBAL







Inspection Date: 25th Sep-, 2013
 Inspector: LEO

Inspection only for: PO . XYK-130819 Item No.1330025	Inspection Result: PASS
--------------------------------------------------------------	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1330025	50PCS	100% inspection	0pcs	No failure	50pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

品名	CNC加工 各種機械加工品 各種機械加工品 CNC加工 CNC 加工品
材質	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
形状	各種形状
用途	各種用途
仕様	各種仕様
加工	各種加工
公差	±0.01mm
表面	各種表面処理
検査	各種検査
納期	各種納期
送料	各種送料
備考	各種備考
1.Name	各種cnc加工
2.Process	各種加工
3.材質	AL6061 AL6065 AL6063 AL7075
4.形状	各種形状
5.Tolerance	±0.01mm
6.表面	各種表面
7.Specification	各種serice
8.公差	25-30
9.検査	各種accessoried
10.納期	Austrial
11.&NBSP;	ISO 9001
品名	
1.形状	ISO
2.形状	
3.形状	kindls available
4.形状	
5.形状	
6.形状	
7.形状	
品名	
形状	&NBSP;
形状	
形状	ISO9001
形状	
形状	