

Inspection Report







Report No.: XYSL-150715
 Supplier : XY-GLOBAL

Inspection Date: 19th Aug, 2015
 Inspector: Leo

Inspection only for: PO . XYSL-150715 Item No. XY31XL035	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31XL035	8000PCS	1% inspection	0pcs	No failure	8000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

品名	CNC加工品CNC加工品
材質	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
形状	
数量	
寸法	
公差	
表面処理	
検査	
納期	
梱包	
送料	
備考	
単位	個
公差	+/-0.01mm
表面処理	50μm 50μm
検査	
寸法	
単位	個
数量	50個 25個
備考	
1. CNC加工品	
2.	
AL6061 AL6065 AL6063 AL7075	
4.	
5. ±0.01mm	
6. 100mm	
7.	
8. 25-30mm	
9.	
10.	
11. ISO 9001	
1.10 ISO	
2.	
3.	
4.	
5.	
6.	
7.	
ISO9001	
OEM	

Safety is our serious job for our worker and engineer team

