

**Inspection Report**







Report No.: XYSL-150717  
 Supplier : XY-GLOBAL

Inspection Date: 22<sup>nd</sup> Aug, 2015  
 Inspector: Leo

Inspection only for: PO . XYSL-150717 Item No. XY31XL037	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31XL037	8000PCS	1% inspection	0pcs	No failure	8000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

項目	内容
材料	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
加工	CNC
公差	+/-0.01
表面処理	阳极酸化
検査	目視検査 二次元検査
包装	個別包装
納期	最短納期
保証	品質保証
送料	送料別
その他	お問い合わせください
1. 加工精度 CNC	
2. 材料の種類	
AL6061 AL6065 AL6063 AL7075	
4. 公差 ±0.01	
5. 表面処理 ±0.01	
6. 検査項目 100%	
7. 包装方法 個別包装	
8. 納期目安 25-30日	
9. 品質保証書 発行可能	
10. 送料 別途見積	
11. ISO 9001 認証取得済み	
お問い合わせ	
1.10 ISO 9001	
2. 品質保証書	
3. 検査項目	
4. 包装方法	
5. 納期	
6. 送料	
7. 表面処理	
お問い合わせ	
品質保証書発行可能	
検査項目	
ISO 9001	
お問い合わせ	
OEM 対応	

Safety is our serious job for our worker and engineer team

