

Inspection Report

Report No.: XYGA-150321
 Supplier : XY-GLOBAL






Inspection Date: 23th Apr., 2015
 Inspector: LEO

Inspection only for: PO . XYGA-140321 Item No. XY21ZC058	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC058	10000pcs	7% inspection	Opes	No failure	10000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :

	
<p>1. Packing</p> 	<p>2. Product:</p> 
<p>3. Product:</p> 	<p>4. Product:</p> 
<p>5. Product :</p>	<p>6. Inspection report:</p>

物料	物料名称CNC加工零件CNC
规格	规格 AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
用途	用途
数量	数量
材质	材质
公差	公差
表面处理	表面处理
包装	包装
交期	交期
备注	备注
1. 物料名称CNC	
2. 物料规格	
物料规格AL6061 AL6065 AL6063 AL7075	
4. 物料用途	
5. 物料公差±0.01	
6. 物料数量100	
7. 物料表面处理	
8. 物料包装25-30	
9. 物料交期	
10. 物料备注	
11. 物料标准ISO 9001	
物料名称	
1.10 物料标准ISO	
2. 物料规格	
3. 物料用途	
4. 物料数量	
5. 物料公差	
6. 物料表面处理	
7. 物料包装	
物料名称	
物料规格	
物料用途	
物料标准ISO9001	
物料数量	
物料OEM	