

**Inspection Report**

**Report No.:** XYN-140616  
**Supplier :** XY-GLOBAL







**Inspection Date:** 11<sup>th</sup> July, 2014  
**Inspector:** Leo

Inspection only for: PO . XYN-140616 Item No.142078	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
142078	8000PCS	1% inspection	0pcs	No failure	8000pcs

<b>Appearance Inspection :</b> No failure.
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

品名	品名 品名 CNC 品名 CNC 品名 CNC
品名	AL6061 AL6065 AL6063 AL7075 &NBSP; SUS304 SUS303 SUS316
品名	
品名	
品名	CNC
品名	gague
品名	
品名	+/-0.01
品名	T / T 50 50 T / T
品名	
品名	
品名	T / T 50 20-25 NBSP
品名	
1.Name 品名 cnc	
2.Process	
品名 AL6061 AL6065 AL6063 AL7075	
4.品名	
5.Tolerance 品名 ±0.01	
6.品名 100	
7.Specification 品名 serice	
8.品名 25-30	
9.品名 accessored	
10.品名 Austrial	
11&NBSP; 品名 ISO 9001	
品名	
1.品名 ISO	
2.品名	
3.品名 kinds available	
4.品名	
5.品名	
6.品名	
7.品名	
品名	
品名 &NBSP; 品名	
品名	
品名 ISO9001	
品名	
品名	