

**Inspection Report**







Report No.: XYNK-130817  
 Supplier : XY-GLOBAL

Inspection Date:15<sup>th</sup> Sep-, 2013  
 Inspector:LEO

Inspection only for: PO . XYNK-130817 Item No.1400489	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1400489	3000Pcs	100% inspection	0pcs	No failure	3000Pcs

<b>Appearance Inspection :</b> No failure.
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

0000	0000000CNC0000000000000CNC00
00	000 AL6061 AL60650AL60630AL70750SUS3040SUS3030SUS3160
00	00000000
0000	00000000000000000000000000
00	0000000000
0000	000000000000000000000000000000 0000
0000	0000000000000000000000 0000000000000000000000000000000000
000000	00000000
00/00	+/-0.0100
0000	00000500000000000000000005000000
0000	00
00	000
00	000000
00	000000050000000250000
0000	00000000
1.0000000000CNC00	
2.000000000000000000	
0000000AL6061 AL60650AL60630AL70750	
4.000000000000000000 0000	
5.0000000±0.0100	
6.000000100000	
7.00000000000000000000000000	
8.00000025-3000	
9.000000000000000000 0000000000000000	
10.0000000000000000000000	
11000000000ISO 9001	
000000	
1.10000000ISO00	
2.000000000000000000	
3.000000000000000000	
4.000000000000	
5.000000	
6.000000	
7.00000000000000	
000000	
000000000000000000000000	
0000000000000000	
00000000000ISO9001	
00000000000000000000	
00OEM00000000	