

Inspection Report

Report No.: XYD-130817
Supplier : XY-GLOBAL

Inspection Date:09th Sep-, 2013
Inspector:LEO

Inspection only for: PO . XYD-130817 Item No.1420039	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1420039	30000PCS	1% inspection	0pcs	No failure	30000pcs

Appearance Inspection : No failure.
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

品名	品名 品名 品名 品名 品名 品名 CNC 品名 CNC 品名 品名 CNC 品名
材質	AL6061 AL6065 AL6063 AL7075 &NBSP; SUS304 SUS303 SUS316
仕様	
数量	
単位	
公差	CNC
表面処理	gague
色	
寸法	+/-0.01
公差	T / T 50 50 T / T
公差	
公差	
公差	T / T 50 20-25 NBSP
公差	
1.Name 品名 cnc	
2.Process	
品名 AL6061 AL6065 AL6063 AL7075	
4.品名	
5.Tolerance ±0.01	
6.品名 100	
7.Specification serice	
8.品名 25-30	
9.品名 accessored	
10.品名 Austrial	
11&NBSP; ISO 9001	
品名	
1.品名 ISO	
2.品名	
3.品名 kinds available	
4.品名	
5.品名	
6.品名	
7.品名	
品名	
品名 &NBSP; 品名	
品名	
品名 ISO9001	
品名	
品名	