



**Inspection Report**







Report No.: XYSK-140526  
 Supplier : XY-GLOBAL

Inspection Date: 28<sup>th</sup> Jun, 2014  
 Inspector: Leo

Inspection only for: PO . XYSK-140526 Item No. XY11WD024	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11WD024	18000PCS	1% inspection	0pcs	No failure	18000pcs

<b>Appearance Inspection :</b> No failure.
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Dimensions report

公司	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXOEMXXXXXXXXXXXX
产品	ADC12 A380
规格	XXXXXXXXXX
数量	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
单位	XXXXXXXXXXXX
材料	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX 100
材料	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX XXXXXXXXXX
材料	XXXXXXXXXX
公差	+/-0.01
长度	50XXXXXXXXXXXXXXXXXXXX50
重量	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
直径	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
厚度	XXXX
长度	50XXXXXXXXXX25
材料	XXXXXXXXXXXXXXXXXXXX
1. 公司 公司名称	
2. 产品 产品名称	
3. 产品规格 ADC12 A380	
4. 材料 材料名称	
5. 公差 $\pm 0.01$	
6. 数量 100	
7. 单位 单位名称	
8. 长度 25-30	
9. 重量 重量	
10. 直径 直径	
11. 材料 ISO 9001	
材料	
1.10 材料 ISO	
2. 材料 材料	
3. 材料 材料	
4. 材料 材料	
5. 材料	
6. 材料	
7. 材料 材料	
材料	
XXXXXXXXXXXXXXXXXXXX	
XXXXXXXXXXXX	
材料 ISO9001	
XXXXXXXXXXXXXXXXXXXX	
OEMXXXXXXXXXXXX	