

**Inspection Report**

Report No.: XYAN-150312  
 Supplier : XY-GLOBAL

Inspection Date: 16<sup>th</sup> Apr., 2015  
 Inspector: LEO

Inspection only for: PO . XYBA-150312      Item No. XY21ZC099	<b>Inspection Result:</b> <b>PASS</b>
--	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC099	12000pcs	7% inspection	0pcs	No failure	12000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

項目	項目 CNC 項目 CNC
項目	項目 AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
項目	項目
項目	項目
項目	項目
項目	項目 項目
項目	項目 項目 項目
項目	項目
項目/項目	+/-0.01
項目	項目 50 項目 50 項目
項目	項目
項目	項目
項目	項目 50 項目 25 項目
項目	項目
1. 項目 CNC	
2. 項目	
項目 AL6061 AL6065 AL6063 AL7075	
4. 項目 項目	
5. 項目 ±0.01	
6. 項目 100	
7. 項目	
8. 項目 25-30	
9. 項目 項目	
10. 項目	
11 項目 ISO 9001	
項目	
1.10 項目 ISO	
2. 項目	
3. 項目	
4. 項目	
5. 項目	
6. 項目	
7. 項目	
項目	
項目	
項目	
項目 ISO 9001	
項目	
項目 OEM	

Safety is our serious job for our worker and engineer team

