

**Inspection Report**

Report No.: XYAN-150309  
 Supplier : XY-GLOBAL

Inspection Date: 10<sup>th</sup> Apr., 2015  
 Inspector: LEO

Inspection only for: PO . XYBA-150309      Item No. XY21ZC096	<b>Inspection Result:</b> <b>PASS</b>
--	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC096	58000pcs	7% inspection	0pcs	No failure	58000pcs

**Appearance Inspection :**  
 No failure,

**Dimension Inspection:**  
 No failure , below measurement report for reference.

**Assembly Test:**  
 No failure

**Inspection Summary**  
 The inspection sample plan is 100% inspection.

Digital photo records :

	
<p>1. Packing</p> 	<p>2. Product:</p> 
<p>3. Product:</p> 	<p>4. Product:</p> 
<p>5. Product :</p>	<p>6. Inspection report:</p>

品名	CNC加工品
材質	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
仕様	
数量	
単位	
公差	
表面処理	
検査	
納期	
備考	
1. 公差	+/-0.01
2. 公差	50
3. 公差	
4. 公差	
5. 公差	
6. 公差	50
7. 公差	25
8. 公差	
9. 公差	
10. 公差	
11. 公差	ISO 9001
1.10. 公差	ISO
2. 公差	
3. 公差	
4. 公差	
5. 公差	
6. 公差	
7. 公差	
公差	
公差	
公差	
公差	ISO9001
公差	
公差	OEM

Safety is our serious job for our worker and engineer team

