

**Inspection Report**







Report No.: XYAN-150311  
 Supplier : XY-GLOBAL

Inspection Date: 16<sup>th</sup> Apr., 2015  
 Inspector: LEO

Inspection only for: PO . XYBA-150311      Item No. XY21ZC098	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC098	12000pcs	7% inspection	0pcs	No failure	12000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

品名	CNC加工品CNC加工品
材質	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
形状	任意
用途	任意
公差	任意
表面処理	任意
検査	任意
納期	任意
送料	任意
備考	任意
数量	任意
単位	個
加工費	±0.01mm
送料	50円
納期	50日
公差	±0.01mm
表面処理	任意
検査	任意
納期	50日
送料	25円
備考	任意
1. CNC加工品	
2. 任意	
3. AL6061 AL6065 AL6063 AL7075	
4. 任意	
5. ±0.01mm	
6. 100円	
7. 任意	
8. 25-30日	
9. 任意	
10. 任意	
11. ISO 9001	
任意	
1.10 ISO	
2. 任意	
3. 任意	
4. 任意	
5. 任意	
6. 任意	
7. 任意	
任意	
任意	
任意	
ISO9001	
任意	
OEM	

Safety is our serious job for our worker and engineer team

