

Inspection Report







Report No.: XYSL-150607
 Supplier : XY-GLOBAL

Inspection Date: 10th July, 2015
 Inspector: Leo

Inspection only for: PO . XYSL-150607 Item No. XY31XL005	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31XL005	32000PCS	1% inspection	0pcs	No failure	32000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

項目	内容
材料	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
加工	CNC加工
公差	+/-0.01mm
表面処理	バリ取り
検査	寸法検査
納期	100個以内
送料	別注
支払条件	前払
保証	1年

- CNC加工
- 材料: AL6061 AL6065 AL6063 AL7075
- 公差: ±0.01mm
- 表面処理: バリ取り
- 検査: 寸法検査
- 納期: 100個以内
- 送料: 別注
- 支払条件: 前払
- 保証: 1年

項目	内容
規格	ISO 9001
品質管理	ISO 9001
検査	寸法検査
納期	100個以内
送料	別注
支払条件	前払
保証	1年

Safety is our serious job for our worker and engineer team

