

Inspection Report

Report No.: XYL-150716
 Supplier : XY-GLOBAL



Inspection Date: 27th Aug, 2015
 Inspector: Leo

Inspection only for: PO . XYL-150716 Item No. XY11LM016	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11LM016	7000PCS	1% inspection	0pcs	No failure	7000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product	6. Report:

品名	○ 加工品 ○ 加工品 OEM 加工品 ○
品名	○ ADC12 ○ A380
品名	加工品
品名	加工品
品名	加工品
品名	CNC 加工品
品名	加工品 gague
MOQ	加工品
公差	+/-0.01
公差	T / T 50 / T / T 50
品名	CNC 加工品
品名	加工品
品名	加工品
品名	20-25 T / T 50
品名	加工品
1.Name	加工品 OEM 加工品
2.Process	加工品
3.品名	加工品 ADC12 A380
4.品名	加工品
5.Tolerance	加工品 +/-0.01
6.品名	加工品 100
7.Specification	加工品 OEM 加工品
8	加工品 25-30
9	加工品 accessoried
10	加工品 Austrial
11.品名	ISO 9001
品名	加工品
1	加工品 ISO 10
2	加工品
3	sureface kinds available
4	加工品
5	加工品
6	加工品
7	加工品
品名	加工品
品名	加工品
品名	加工品 ISO9001
品名	加工品
品名	加工品 OEM 加工品

Safety is our serious job for our worker and engineer team

