

**Inspection Report**

Report No.: XYL-150807  
 Supplier : XY-GLOBAL







Inspection Date: 17<sup>th</sup> Sep, 2015  
 Inspector: Leo

Inspection only for: PO . XYL-150807 Item No. XY11XL050	<u>Inspection Result:</u> PASS
------------------------------------------------------------	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11XL050	18000PCS	1% inspection	0pcs	No failure	18000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :

	
<p>1. Packing</p> 	<p>2. Product</p> 
<p>3. Product</p> 	<p>4 Product</p> 
<p>5. Product:</p>	<p>6. Report:</p>





High qualified surface treatment can make your parts perfect !!!

