

Inspection Report

Report No.: XYN-130820
 Supplier : XY-GLOBAL

Inspection Date: 15th Sep., 2013
 Inspector: LEO

Inspection only for: PO . XYN-130820 Item No.1400157	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1400157	8000PCS	1% inspection	0pcs	No failure	8000pcs

Appearance Inspection : No failure.
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

品名	品名 CNC加工品 CNC加工品
材質	AL6061 AL6065 AL6063 AL7075 &NBSP; SUS304 SUS303 SUS316
仕様	
数量	
単位	
加工方法	CNC加工
加工条件	gague
公差	
公差	+/-0.01
公差	T / T 50 T / T 50 T / T
公差	
公差	
公差	T / T 50 20-25 NBSP
公差	
1.Name CNC加工品	
2.Process	
AL6061 AL6065 AL6063 AL7075	
4.	
5.Tolerance ±0.01	
6.100	
7.Specification serice	
8.25-30	
9.accessoried	
10.Austrial	
11&NBSP; ISO 9001	
品名	
1.10 ISO	
2.	
3.kinds available	
4.	
5.	
6.	
7.	
品名	
&NBSP;	
ISO9001	